



12'-0"

Varies With Pattern  
4'-0" Max



Actual Pattern May Vary

### Typical Section




# #719 LONGMEADOW


## 24'-0"

A noticeable seam will occur if not properly sealed when stacking liners.

Varies With Pattern

### 8'-0" Max

A noticeable seam will occur if not properly sealed when stacking liners.




A noticeable seam will occur if not properly sealed when stacking liners.

A noticeable seam will occur if not properly sealed when stacking liners.

Plastic formliners MUST be stored at a temperature range of 55° to 85° Fahrenheit. Failure to do so will result in permanent distortion to these plastic formliners and will warrant them both unusable and destroyed. Therefore, AP Thermoforming will NOT assume any liability for damaged formliners caused from improper storage

## ITEM # 305603



1035 Little Gap Highway  
 Palmerton PA, 18071  
 610-826-4579  
 Fax: 610-826-4614

Customer:	
Job Name:	
Title:	719 Longmeadow Assembled

Drawn By:		Date:	
Approved By:		Date:	
Scale:	None	Tolerance:	±3/16
Page:	2	Drawing Number:	